

PLEATED BLIND FASTENING SYSTEMS





no. 03 - 2024 subject to change



NEW

universal adhesive clamping shoe	
for all standard pleated blind systems	page 4
universal adhesive plate	
for pleated blinds	page 6
adhesive plate	
for plissee system Cosiflor®	page 8
adhesive plate	
for plissee system Decomatic®	page 10
adhesive plate	
for plissee system EOS [®]	page 12
universal adhesive bracket	
for rounded or small window bars	page 14
clamp bracket	
for pleated and venetian blinds	page 16
glider	
for pleated and venetian blinds	page 19

universal clamping shoe for gluing or screwing

- suitable for all standard pleated blind systems
- for adhesive mounting: Recommended max. pleated blind size 2 m²
- assembling on the glazing bead: Depth at least 13 mm



NEW







article	article no. description	dispatch unit
Image:	565 RKS universal clamping shoe Scope of delivery: • clamping shoe • cleaning tissue • self-adhesive film • fastening srews	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	565 KS universal clamping shoe Scope of delivery: • clamping shoe • self-adhesive film • fastening srews	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	 565 S universal clamping shoe Scope of delivery: clamping shoe fastening srews 	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest solvent isopropanol	5 pieces in a bag - 100 pieces in a box

Made in Germany

universal clamping shoe for gluing or screwing

- suitable for all standard pleated blind systems
- for adhesive mounting: Recommended max. pleated blind size 2 m²
- assembling on the glazing bead: Depth at least 13 mm




NEW

Important when using the adhesive films:

The double-sided adhesive films are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough. When using the adhesive films please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles. After using solvents, the cleaned surfaces must be allowed to air for at least 2 hours befor they are covered. If possible, do not touch any of the adhesive surfaces so that the adhesive strength is not reduced.



Clean the window frame (with the enclosed cleaning tissue).



Remove the existing carriers from your pleated blind system and knot the cord ends again*.



Adhesive clamping shoe below



Attach the double-sided adhesive film to the lower parts and press firmly.



Clamp the knotted cord ends into the four caps of the adhesive clamping shoes.



Adhesive clamping shoe top



Remove the yellow protective film. Press firmly at the right position for at least 20 seconds.



Insert the caps with the cords into the guide and clip them in.



*For pleated blinds which are not made to measure, please also look at the enclosed instructions for shortening.

universal adhesive plate for pleated blinds for system **Cosiflor**[®] and **Decomatic**[®]



(max. size of the pleated blind 2m²)



article	article no. description	dispatch unit
La restant	 561 UV universal adhesive plate for pleated blinds transparent Scope of delivery: adhesive plate self-adhesive film srews and nuts for fastening the clamping shoes* 	4 pieces in a bag - 100 pieces (= 25 bags) in a box
La Talina La Talina La Talina La Talina La Talina La Talina	 SBB 561 UV universal adhesive plate for pleated blinds transparent 4 pieces in a blister pack • Scope of delivery: adhesive plate self-adhesive film srews and nuts for fastening the clamping shoes* 	4 pieces in a blister pack - 10 blister packs in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest solvent isopropanol	5 pieces in a bag - 100 pieces in a box

*clamping shoes are delivered with the pleated blind


universal adhesive plate for pleated blinds for system **Cosiflor**[®] and **Decomatic**[®]



(max. size of the pleated blind 2m²)



Glue plates for pleated blinds are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough (depth of the window bar at least 13 mm). When using the glue plates please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles! (After using solvents the purified surfaces have to dry for at least 2 hours.)



- (1) The enclosed adhesive film has to be take off from the carrier film. Put it on the adhesive plate (if possible do not touch the sticky side, not to reduce the adhesive force). Press strongly and rub over it several times!
- (2) Remove the protective film and press the adhesive plate on the marked position on the window bar 20 seconds at least (hole for the screw-nut must be in the front). Ideal temperature at 20°C, heat accelerates the adhesive process.

(3a) clamping shoe* system COSIFLOR® • hole in the middle • long lens head screw • Image: A mage: A mage:

(3b) clamping shoe* system DECOMATIC®



(3) Insert the nut into the adhesive plate and mount the clamping shoe* on the plate. Make absolutely sure that the screw is not tightened too much, because the glueplate might be damaged!

adhesive plate for pleated blinds system **Cosiflor**®



(max. size of the pleated blind 2m²)



clamping Cosiflor [®]	clamping Cosiflor [®]
new type	old type
6,2mm 6,2mm ise article 570	vse article 567


article	article no. description	dispatch unit
6,2mm	570 adhesive plate for system Cosiflor® with clamping shoe <u>new type</u> transparent incl. self adhesive film	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	 SBB 570 adhesive plate for system Cosiflor® with clamping shoe <u>new type</u> transparent incl. self adhesive film • 4 pieces in a blister pack • 	4 pieces in a blister pack - 10 blister packs in a box
7,2mm	567 adhesive plate for system Cosiflor® with clamping shoe <u>old type</u> transparent incl. self adhesive film	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	 SBB 567 adhesive plate for system Cosiflor[®] with clamping shoe <u>old type</u> transparent incl. self adhesive film • 4 pieces in a blister pack • 	4 pieces in a blister pack - 10 blister packs in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest, solvent isopropanol	5 pieces in a bag - 100 pieces in a box

adhesive plate for pleated blinds system **Cosiflor**[®]




6,2 mm

(max. size of the pleated blind 2m²)



Glue plates for pleated blinds are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough (depth of the window bar at least 13 mm). When using the glue plates please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles! (After using solvents the purified surfaces have to dry for at least 2 hours.)



- (1) The enclosed adhesive film has to be take off from the carrier film. Put it on the adhesive plate (if possible do not touch the sticky side, not to reduce the adhesive force). Press strongly and rub over it several times!
- (2) Remove the protective film and press the adhesive plate on the marked position on the window bar 20 seconds at least. Make sure that the arrow on the adhesive plate points outwards to the window frame (see illustrations). Ideal temperature at 20°C, heat accelerates the adhesive process.
- (3) Clip the base part of the Cosiflor® clamping shoe* at the adhesive plate. Pay attention at the correct position!



(4) Mount the Cosiflor® pleated blind.

clamping shoes are delivered with the pleated blind.

adhesive plate for pleated blinds system **Decomatic**®



(max. size of the pleated blind 2m²)



article	article no. description	dispatch unit
taat	569 adhesive plate for system Decomatic [®] transparent incl. self adhesive film	4 pieces in a bag - 100 pieces (= 25 bags) in a box
Lind Lind	 SBB 569 adhesive plate for system Decomatic[®] transparent incl. self adhesive film 4 pieces in a blister pack • 	4 pieces in a blister pack - 10 blister packs in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest solvent isopropanol	5 pieces in a bag - 100 pieces in a box


adhesive plate for pleated blinds system **Decomatic**®



(max. size of the pleated blind 2m²)



Glue plates for pleated blinds are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough (depth of the window bar at least 13 mm). When using the glue plates please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles! (After using solvents the purified surfaces have to dry for at least 2 hours.)



- (1) The enclosed adhesive film has to be take off from the carrier film. Put it on the adhesive plate (if possible do not touch the sticky side, not to reduce the adhesive force). Press strongly and rub over it several times!
- (2) Remove the protective film and press the adhesive plate on the marked position on the window bar 20 seconds at least. Make sure that the arrow on the adhesive plate points outwards to the window frame (see illustrations). Ideal temperature at 20°C, heat accelerates the adhesive process



(3) Mount the Decomatic[®] pleated blind.

adhesive plate for pleated blinds system **EOS**[®]



(max. size of the pleated blind 2m²)



article	article no. description	dispatch unit
	564 adhesive plate for system EOS [®] transparent incl. self adhesive film	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	SBB 564 adhesive plate for system EOS [®] transparent incl. self adhesive film • 4 pieces in a blister pack •	4 pieces in a blister pack - 10 blister packs in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest solvent isopropanol	5 pieces in a bag - 100 pieces in a box


adhesive plate for pleated blinds system **EOS**[®]



(max. size of the pleated blind 2m²)



Glue plates for pleated blinds are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough (depth of the window bar at least 13 mm). When using the glue plates please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles! (After using solvents the purified surfaces have to dry for at least 2 hours.)



- (1) The enclosed adhesive film has to be take off from the carrier film. Put it on the adhesive plate (if possible do not touch the sticky side, not to reduce the adhesive force). Press strongly and rub over it several times!
- (2) Remove the protective film and press the adhesive plate on the marked position on the window bar 20 seconds at least. Make sure that the arrow on the adhesive plate points outwards to the window frame (see illustrations). Ideal temperature at 20°C, heat accelerates the adhesive process



(3) Mount the EOS[®] pleated blind.

universal adhesive plate for pleated blinds for system **Cosiflor**[®] and **Decomatic**[®]





Useable for rounded or small window bars e.g. at triple glazing.




article	article no. description	dispatch unit
	562 adhesive plate for pleated blinds self adhesive with screws and nuts for fastening the clamping shoes* colno. 1.00 white colno. 2.35 grey colno. 8.00 brown colno.14.19 anthracite	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	SBB 562 adhesive plate for pleated blinds self adhesive • 4 pieces in a blister pack • with screws and nuts for fastening the clamping shoes* colno. 1.00 white colno. 2.35 grey colno. 8.00 brown colno.14.19 anthracite	4 pieces in a blister pack - 10 blister packs in a box
	561 KLE self-adhesive film transparent	100 pieces
	539 cleaning tissue removes adhesive rest solvent isopropanol	5 pieces in a bag - 100 pieces in a box

*clamping shoes are delivered with the pleated blind

universal adhesive plate for pleated blinds for system **Cosiflor**[®] and **Decomatic**[®]



Adhesive brackets for pleated blinds are usable for plastic and aluminium window frames which are not special coated, veined, uneven or rough (depth of the window bar at least 13 mm). When using the glue plates please make sure that the surfaces are dry and clean. They have to be free from e.g. grease, oil or silicone films, as well as dirt particles! (After using solvents the purified surfaces have to dry for at least 2 hours.)



- (2) Place the nut at the corresponding position. The position of the nut depends on the used pleated blind system. Then mount the base part of the clamp shoe* note left and right ! Make sure that the screw is not tightened too much, because the bracket might be damaged!
- (3) Attach the adhesive bracket at the window frame (note left an right). Press on strongly 20 seconds at least.

clamp bracket for system Cosiflor® and Decomatic®







useable for pleated blinds and venetian blinds

article	article no. description	dispatch unit
	566 clamp bracket, white for pleated blinds and venetian blinds with bolt and nut for fixing the clamping shoes*	4 pieces in a bag - 100 pieces (= 25 bags) in a box
	 SBB 566 clamp bracket, white for pleated blinds and venetian blinds 4 pieces in a blister pack • with bolt and nut for fixing the clamping shoes* 	4 pieces in a blister pack - 10 blister pack in a box

clamp bracket for system Cosiflor® and Decomatic®




Clamp brackets are suitable for a clamp range (width of profile of the window) from 10 mm to 25 mm.




\Lambda Don´t use an electric srewdriver!



mounting example system COSIFLOR®



hole in the middle for clamping shoes COSIFLOR® holes on the side for clamping shoes DECOMATIC®



glider for pleated and venetian blinds





to move laterally in alu-rails and alu-rail-rods with a run of 6 mm

article	article no. description	dispatch unit
Charles and the second	20 GJ glider for pleated blinds and venetian blinds	2 pieces in a bag - 20 pieces (= 10 bags) in a box

